



## PMA Supplement Listing Alabama Supplement #36

Jet Parts Engineering, Inc.  
25303 Profit Drive  
Daphne, AL 36526

PMA NO. PQ1739CE  
Supplement #36  
Issued: January 11, 2008

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Plate, Piston Shoe Retaining (Standard)	887332JP	EATON/Vickers 887332	Airbus	A330 A340
Plate, Piston Shoe Retaining (0.001 Oversize)	342213JP	EATON/Vickers 342213	Airbus	A330 A340
Plate, Piston Shoe Retaining (0.004 Oversize)	622436JP	EATON/Vickers 622436	Airbus	A330 A340
Plate, Piston Shoe Retaining (0.006 Oversize)	342214JP	EATON/Vickers 342214	Airbus	A330 A340
Plate, Piston Shoe Retaining (0.011 Oversize)	342215JP	EATON/Vickers 342215	Airbus	A330 A340
Ring	329272JP	EATON/Vickers 329272	Boeing  Airbus	737-600/700/800/900 757-200/200PF/300 747-400 767-200/300/400 MD-11 A300-600 A310 A319, A320, A321

\*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact [sales@jetpartsengineering.com](mailto:sales@jetpartsengineering.com) or call 206-281-0963.

## PMA Supplement Listing Alabama Supplement #36

<u>PMA Part Name</u>	<u>PMA Part Number</u>	<u>Approved Replacement for (OEM) Part Number</u>	<u>Make Eligibility</u>	<u>Model Eligibility</u>
Gasket	353849JP	EATON/Vickers 353849	Boeing	737-600/700/800/900 757-200/200PF/300 747-400 767-200/300/400 MD-11
			Airbus	A300-600 A310 A319, A320, A321
Ring, Sealing	517980JP	EATON/Vickers 517980	Boeing	757-200/200PF/300 747-400 767-200/300/400 MD-11
			Airbus	A300-600 A310
Packing	890519JP	EATON/Vickers 890519	Boeing	757-200/200PF/300 747-400 767-200/300/400 MD-11
			Airbus	A319, A320, A321

\*This supplement listing is not endorsed by the FAA. For the original copy of the Jet Parts Engineering supplement, please contact [sales@jetpartsengineering.com](mailto:sales@jetpartsengineering.com) or call 206-281-0963.